

Nordale Road Rehabilitation Project



Bridge Abutment at the Chena River Showing Erosion



Exposed Bridge Abutments at the Little Chena River

Figure 2: Bridge Abutment Photos, Chena River Bridge, Nordale Road, North Pole